


To WHOM SO EVER IT MAY CONCERN

BUILDING SAFETY CERTIFICATE

It is certified that the building and boundary wall of "Kendriya Vidyalaya Mandi" Distt. Mandi (HP) as reported by the Assistant Engineer, Kamand Sub-Division, HPPWD Kamand seems to be safe to run school classes under normal condition for the year 2019-2020 as per the visual inspection of the building. However structural stability cannot be ascertained due to non-availability of structural design, drawings and IS specification required for the building construction. This certificate is being issued purely on the basis of visual inspection and issuance of this certificate does not confer any legal and financial liabilities on the issuer please.


Executive Engineer,
Mandi Division No-1
HPPWD Mandi.

No.PW/MDI-I/WA-I/Education/2019

6409-10

Dated:- 5/8/19

Copy to the Assistant Engineer, Kamand Sub-Division, HPPWD Kamand w.r.t. his office letter No.743 dated 31.07.2019.

✓ Copy to the Principal, kendriya Vidyalaya Mandi , Distt. Mandi (HP) for information w.r.t. his office letter No. 19 dated 14.05.2019.


Executive Engineer,
Mandi Division No-1
HPPWD Mandi